



Safety Instructions



0,1,2,3,4,6,7,8,
11,15,22,26,27



Info Hotline 

+49 (0) 5041 998 389

Mon. - Do. 7⁰⁰ - 20⁰⁰

Fr. 7⁰⁰ - 17⁰⁰

Paulmann Licht GmbH
31832 Springe / Germany
www.paulmann.com

Art.-Nr.:

750.50

















750.80


750.00

750.60

(+MA 173)

PKL 01/13 



| | |
|---|-------------------------|
|  | Art. No. |
| | 1415W 436mm G13 885.15 |
| | 1418W 588mm G13 885.41 |
| | 1430W 893mm G13 885.20 |
| | 1436W 1198mm G13 885.50 |

Instruction for luminaire service

| Replace aged or failed lamp | Switch Off switch off supply to luminaire | Open Luminaire | Remove old lamp send to recycling centre | Fit new lamp Insert the new lamp into lamp holder | Refit optic | Make Functional test |
|-----------------------------|--|----------------|---|--|-------------|----------------------|
| | | | | | | |

Instruction for luminaire cleaning

| Clean Luminaire | Switch Off switch off supply to luminaire | Wipe outside optic | Remove optic | Clean inside luminaire | Refit Optic | Make Functional test |
|-----------------|--|--------------------|--------------|------------------------|-------------|----------------------|
| | | | | | | |

Instruction for end of life and components disposal

| Switch Off switch off supply to luminaire | Remove lamp for disposal | Remove battery for disposal | Remove luminaire for disposal | Dispatch materials to WEEE recycling plant |
|--|-----------------------------|--------------------------------|----------------------------------|---|
| | | | | |